


## 4th Level Right Room Facts & Features



This was designed as a bedroom.

They were not sure in 1868 if the cast iron would be strong enough, so an inside brick layer was added. Insulation was an additional benefit.

The gray ring you see all the way around is a flange from outside plates locking into the brick layer, every 8 feet.

There is a 1½ inch gap between the brick and the iron.